


Although 0985 and 1112 have similar physical characteristics, these drives are different. The difference is where shift lever fork slides onto drive:







If you try to apply one for the other, the fork will not fit.